	Walver-	linensure, onl	4	waves reg fa		
<u>_Divisio</u>	n of Health Care Fac NTOF DEFICIENCIES	Ilities 30 1/	02/17	tag N848 waver rog til 1/31/17 approvedig	I'RINTED FORM): 12/ 22. [APPRO
AND PLAN OF CORRECTION IDENTIFICATION NUMBER. TN7505		(X2) MULTIPLE CONSTRUCTION A. BUILDING, 01 - MAIN BUILDING 01		TIAN DATE	. SUHW. \	
		TM7EGE			COMPLETED	
		FI WING		R 12/22/2010		
	ALTHCARE, MURFRE	\$ (REE.) AL	iorfas, cit IIVERSITY	Y. SIATE, ZIP CODE		
		MURFRE		TN 37130		
(X4) (D PREDIX	I RAGIT OF HIGHNICY	TEMPNY OF DEFICIENCIES YMUSY OC PRECEDED BY FUIL	ID PROVIDER'S PLAN OF COPPECTION			
TAG	KEGOEATORY (III)	SC (DENTIFYING INFORMATION)	PREFIX	(EAGH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPRO DEFICIENCY)	m a	XX) PAMOO TAO
	1200 8-608 (1) Building Standards (1) A nursing home shall construct, arrange, and		(N R31)	Plan of Correction N8		
	the overall nursing himanner that the safe residents are assure	on or the physical plant and nome environment in such a pty and well-being of the sid.		The center does construct, arrange and maintain the condition of the physical plant and the overall center environment in such a manner that the safety and well being of the residents are ensured. Fire Stop Technologies repaired the penetrations in the cross corridor fire barrier wall the following areas		
t c e t c e t c c c e t c c c e t c c c e t c c c e t c c c e t c c c e t c c c e t c c c e t c c c e t c c c c	The findings Included The findings Included Cobservation on 10 the following holes in ceiling at room 219: 3 "x3" 8 "x4" 2 8"x4" 1 2"x2" IFPA 101, 19.3.6.2.1	is, the facility falled to I plant and overall it: /31/16 at 12.30 PM, revealed the conidor walls above the (2000 Edition)		1.) Corridor Wall by 219 were repaired 12/23/16 a. 3'x 3' b. 8'x 4' c. 2' x 2' 2.) 2 East Nurse Station on 2 nd floor: a repaired on 12/23/16 a. 8 (1/2/) inch conduits b. 1 data wire c. ½ inch sleeve d. 1 x ½ inch fole c. Wall to wall joint scam (End POC N831) As part of the eneter's	vere	
b a. b. c. d. e.	arrier wall next to Ca . 6 (1/2 inch conduits . 1 data wire . 1/2 inch sleeve . 1x1/2 inch hole	ons in the cross corridor fire station 2nd floor:) (mixed fireston) NEDA		ongoing Quality Assurance, Administrated Director of Maintenance reviewed a scope of all K-tag on the survey. Maintenance will in-service all plant operations of regarding each tag. Maintenance D will incorporate issues regarding wall penetrations in the center's ongoing maintenance logs. Maintenance Directed also review the cited tags with any contribat will provide any work at the center,	tor he enance on irector	
by	aintonance staff was ficiencies were ident the administrator du Care Facilillas	present when the iffied, and acknowledged ring the exit conference on		Pirestop Technologies will be contacted new areas need to be reviewed and will maintain any new or damaged penetration		

01/18/2017 WHD 14:17 FAX 8655942168 Dept. of Health

Ø004/004

PRINTED: 12/22/2018 FORM APPROVED

STATEME	NT OF DEFICIENCIES	(X1) PROVIDER/SUPPLIER/CLIA	(Non-Agenta-	DI E ARVENIE		APPROV
ANນ ቦኒለአ	OF CORRECTION	IDENTIFICATION NUMBER.	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 - MAIN BUILDING 01 D. WING		(X3) DATE STRIVEY COMPLETED	
		TN7505				
NAME OF PROVIDER OR SUPPLIER		·	STREET ADDRESS, CITY, STATE, ZIP CODE.			<u>22/2016</u>
	ALTHOARE, MURFRE	WINCEIP	moress, city NIVERSITY :	', STATE, ZIP COUL ST		
,		MURFR	FESBORO, 1	FN 37430		
(X4) (D PREHIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FREE REGULATORY OR LSC IDENTIFYING INFORMATION)		PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(XS) · COMPLET DATE
(N 831)	Confinued From page 1		(N 831)			
	10/31/16.			the future. A log of UI, Systems and add any systems or engineer	ine	ł
T C continue of the continue o	1200-8-608 (18) Building Standards		(N 848)	judgements not included in syste	ms book,	12/23 /:
	(18) It shall be demonstrated through the submission of plans and specifications that in each nursing home a negative air pressure shall be maintained in the soiled utility area, toilet room, janifor's closet, dishwashing and other such soiled spaces, and a positive air pressure shall be maintained in all clean areas including, but not limited to, clean linen rooms and clean utility rooms.			Plan of Correction ?	Plan of Correction N848 the center engaged an engineer and contractor make the needed balancing for negative air ow in the clean linen room beside 116. The	
				to make the needed balancing for flow in the clean linen room besi-		
				work was completed on 1/26/16 by UTA meet the specific requirements.		1/26/1
	This Rule is not mot Based on observation naintain the clean lin	as evidenced by: ha, the facility falled to non room as required,				
	The finding inleuded:				Ì	
	near men smisite M	I/16 at 11:01 AM, revealed ithout a cloan air supply in on closet beside patient				
	faintenance staff wa eficiency was identifi te administrator duri 0/31/16.	s present when the led, and acknowledged by ng the exit contenence on				
E)	xtension expires 01/	31/17				
ı of Healti	Care Facilities	 , l_		<u> </u>	Ī	